

GEMWOODS LAMINATE MAINTENANCE AND CLEANING

Scottsdale, Flagstaff, Prescott, Santa Fe, Del Mar, Kauai

Preferable temperature should be approximately 62-73 F° (17-23 C°) with a relative humidity of 45-60 percent. Humidity should never be allowed to drop below 30% as this may cause gapping.

Do not use a wet spray micro fiber mop. Use a well rung out damp cloth to clean up any dirt and footprints but avoid using excessive moisture. All spills should be cleaned up immediately. Never use wax, polish or scouring agents as they may dull or distort the finish. You can use acetone or a cleaner specially formulated for laminate to remove stubborn marks.

To avoid scratches apply felt pads to your furniture legs and use only soft rubber casters. Protect high traffic areas with runners and area rugs.

It is a good idea to save a few boards in case of accidental damage. Boards can be replaced or repaired by a flooring professional.

January 2014